

Technical Considerations

Due to the peaks of temperature and to the blow-by, the lubricating oil has the tendency to progressively degrade forming some sludges, muds and crusts which limit the lubrication system to properly work. Inadequate lubrication is synonym of early wear and eventual crushing of any bearing like that one of the turbocharger.

Before oil replacement it is convenient to clean the oil ducts. Lazy piston rings loosened too thus reducing the blow-by. Noisy valve adjusters stop their irritant knocking.