

Technical Considerations

On hydraulic appliances it is necessary the use of light oils which, even if mixed with special additives, at high temperature the progressively loose their lubricating capacity. Consequently the appliance do not correctly work as the pump, valves, pistons, seals, etc. are affected by wear. The stick-slip starts up , the noisy level rises up, etc.