

Technical Considerations

On Two Stroke engine the lubrication of engine is done by the oil mixed to the gasoline. Especially due to the high peaks of temperature the oil do not guarantees an efficient lubrication thus causing an early wear . X35 coats metal surfaces thus preserving the running parts from contact and relative wear. At the same time the coating layer improves the seal between piston and cylinder generating a positive rise of compression.